



VEHICLE INSPECTION REPORT

GU72WWH

Toyota C-Hr 1.8 Hybrid Design 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/09/2022	VIN	NMTK33BX90R218865	CAP Average	£17,900.00
Year	2022	Body Style	Hatchback	CAP Below	£16,550.00
Mileage	11,838 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Hybrid Electric	Service history	None	Gears	1
Colour	MAUVE/PURPLE	CAP Clean	£19,250.00	Doors	5

First MOT Not Due
No Service History


Tyres


NSF	MICHELIN	2.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Trip computer
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Rear wiper
- Auxiliary input socket
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Corroded
Light



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Dented
With Paint Damage




7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm

No Image

9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image

11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Over 50mm




13: Door osr
Dented
With Paint Damage



14: Qtr Panel Trim os
Scuffed
Over 25mm



15: Door osf
Dented
Over 2 UpTo 10mm



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Dented
Over 30mm



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK