



VEHICLE INSPECTION REPORT

GY09OKM

Volvo XC60 D5 [205] SE Lux Premium 5dr AWD Geartronic



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	24/07/2009	Body Style	Estate	Last service miles	140,836
Year	2009	Keys	2	MOT Due	31/10/2026
Mileage	148,830 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	7		
VIN	YV1DZ7046A2055168	Last service date	01/11/2022		

LAST SERVICE - 01/11/2022 @ 140,836 MILES (7 SERVICES) Sunroof faulty
 City safety service required message displayed
 Boot lock faulty
 Display screen stuck

Tyres



NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Electric sunroof
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Flasher Side Repeater ns
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
Multiple Chips



9: Switches And Controls
Missing
Replace



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Poor Previous Repair
Poor Paint



12: Lamp nsr
Broken
Replace



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Tailgate
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osf
Scratched
Over 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: Door osf
Scratched
Over 25mm Thru Paint




18: Door osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5



21: Roof
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK