



# VEHICLE INSPECTION REPORT

**RV13PXP**

## Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	17/04/2013	Body Style	Hatchback	Last service miles	84,720
Year	2013	Keys	2	MOT Due	31/10/2026
Mileage	92,992 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	10	Doors	5
VIN	WF0DXXGAKDDM89013	Last service date	08/01/2025		

£100 ADDITIONAL FEE.

Last Service - 08.01.2025 at 84720 miles (10 services) EML light on car has been plugged in and detects Catalyst system efficiency below threshold bank 1  
 Intermittent Engine noise on start up then goes after being sat idle

### Tyres


NSF	BUDGET	1.7mm
NSR	FULLRUN	4.0mm
OSF	FULLRUN	2.0mm
OSR	AVON	4.0mm
Spare		

## Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel of  
Scratched  
Over 50mm



2: Wing of  
Chipped  
1 To 5



3: A Post os  
Chipped  
1 To 5



4: Door osf  
Scratched  
Over 25mm Thru Paint



5: Door osr  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Bumper Rear  
Chipped  
Multiple Chips




9: Tailgate  
Poor Previous Repair  
Poor Paint



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsr  
Chipped  
Multiple Chips



12: Door nsf  
Chipped  
Edge Chip



13: Door Mirror Assy nsf  
Scratched (Painted)  
Up To 25mm Thru Paint



14: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



15: Bonnet  
Scratched  
Over 25mm Thru Paint



16: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



17: Bumper Front  
Chipped  
Multiple Chips



18: Roof  
Scratched  
Over 25mm Not Thru Paint



19: Wheel nsf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK