

VEHICLE INSPECTION REPORT

FH660TR

Fiat Tipo 1.4 Easy Plus 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	16/12/2016	Body Style	Hatchback	MOT Due	04/07/2026
Year	2016	Keys	2	Gearbox	MANUAL
Mileage	100,598 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Service Book	Doors	5
Colour	RED	Number of stamps	11		
VIN	ZFA35600006E50756	Last service miles	98,494		

Last Service - Unkonwn at 98494 miles (11 services)

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	4.0mm


Spare

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm




11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Dented
With Paint Damage



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Dented
Over 30mm



18: Wing osf
Chipped
Multiple Chips



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm



21: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK