



# VEHICLE INSPECTION REPORT

**FW13ENE**

## Volkswagen Passat 1.6 TDI Bluemotion Tech S 5dr

nama  
 GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	18/07/2013	Body Style	Estate	Last service miles	103,336
Year	2013	Keys	2	MOT Due	27/07/2026
Mileage	104,473 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	13		
VIN	WVVZZZ3CZDE151024	Last service date	12/02/2026		

£100 ADDITIONAL FEE

last service 12/2/26 @ 103,336 miles (13 services 6 main dealer) book

### Tyres


NSF	RAPID	4.0mm
NSR	YOKOHAMA	5.0mm
OSF	RAPID	4.0mm
OSR	YOKOHAMA	5.0mm
Spare		

### Features


- Bluetooth connection
- Radio/CD
- Heated door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Central locking
- PAS
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Remote central locking
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Rear  
Scratched  
Over 100mm Thru Paint



3: Other  
N/A  
N/A



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
UpTo 25mm Thru Paint




8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Cracked  
UpTo 25mm



10: Tailgate  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osf  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Dented  
Over 30mm



13: Door osf  
Chipped  
Multiple Chips



14: Wheel osf  
Scratched  
Over 50mm



15: Wing osf  
Scratched  
Over 25mm Thru Paint



16: Screen Front  
Chipped  
UpTo 10mm



17: Roof  
Chipped  
1 To 5

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK