



VEHICLE INSPECTION REPORT

LR13NDO

Mazda 6 2.2d [175] Sport Nav 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	08/05/2013	Colour	GREY	Service history	None
Year	2013	VIN	JMZGJ692621126041	MOT Due	02/02/2027
Mileage	124,734 Miles Warranted	Body Style	Estate	Gearbox	MANUAL
Fuel Type	Diesel	Keys	1	Gears	6

No Services History I stop warning light display
 Oil change due
 I-loop inspection required

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Dented
With Paint Damage




3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Rear TowEye Cvr
Missing
Replace



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Tailgate
Cracked
Replace




12: Qtr Panel osr
Dented
Over 30mm



13: Roof
Dented
Over 30mm



14: Door osr
Dented
With Paint Damage



15: Door osf
Dented
With Paint Damage



16: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Over 50mm



19: A Post os
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK