



VEHICLE INSPECTION REPORT

YF09SVW

BMW 3 Series 318d M Sport 4dr Step Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	16/07/2009	VIN	WBAPN12080A597232	Number of stamps	4
Year	2009	Body Style	Saloon	MOT Due	18/07/2026
Mileage	152,610 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service history	Yes	Gears	6
Colour	GREY	Service documents	Service Book	Doors	4

LAST SERVICE 14/07/2020 @ 130,704 MILES (4 SERVICES) Residue over most panels on car

Car is very lumpy when driving

Abs light on

EML light on car has been plugged in and detects intake air system leak

Radio does not work

Exhaust pressure sensor range performance

Tyres

NSF	AVON	5.0mm
NSR	NEXEN	4.0mm
OSF	AVON	5.0mm
OSR	NEXEN	4.0mm

Spare

Features


- PAS
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Up To 50mm



6: Qtr Panel osr
Dented
Between 10mm + 30mm



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsf
Chipped
1 To 5




10: Door nsf
Dented
Between 10mm + 30mm



11: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm




13: Wing nsf
Chipped
1 To 5



14: Bumper Front
Dented
With Paint Damage



15: Bonnet
Chipped
Multiple Chips



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK