



VEHICLE INSPECTION REPORT

GU64TLJ

Honda Jazz 1.4 i-VTEC ES Plus 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/09/2014	Body Style	Hatchback	Last service miles	81,639
Year	2014	Keys	2	MOT Due	28/09/2026
Mileage	88,474 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BROWN	Number of stamps	11	Doors	5
VIN	SHHGG6760EU018547	Last service date	11/09/2025		

LAST SERVICE 11/09/2025 @ 81,639 MILES (11 SERVICES, ALL MAIN DEALER) Ignition barrel is stiff
 Boot will not open
 Some panel required machine polish

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	MAXXIS	4.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Chipped
Multiple Chips



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Dented
With Paint Damage



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Door nsf
Chipped
1 To 5



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5



15: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: A Post os
Chipped
Edge Chip



18: A Post ns
Chipped
Edge Chip



19: Roof
Dented
Between 10mm + 30mm



20: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK