

# VEHICLE INSPECTION REPORT

**LL64YRW**

## Ford C-Max 2.0 TDCi Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	16/01/2015	Colour	BLACK	Service history	None
Year	2015	VIN	WF0JXXGCBJEG67802	MOT Due	21/05/2026
Mileage	74,427 Miles Warranted	Body Style	MPV	Gearbox	AUTOMATIC
Fuel Type	Diesel	Keys	2	Gears	6

### £100 ADDITIONAL FEE

No Service History Some panels require machine polish

Tyre sensors malfunctioning

Steering faulty hard to turn the wheel when first switching on the car

### Tyres


NSF	LAUFENN	Damaged
NSR	LAUFENN	3.0mm
OSF	RAPID	5.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door Mirror Assy nsf  
Broken  
Replace



6: Door nsf  
Scratched  
Up To 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Tailgate  
Poor Previous Repair  
Poor Paint



12: Qtr Panel osr  
Scratched  
Rusted



13: Door osr  
Scratched  
Up To 25mm Thru Paint



14: Door osf  
Chipped  
Edge Chip



15: Wing osf  
Chipped  
1 To 5



16: Wheel osf  
Scratched  
Over 50mm



17: Tyre nsf  
Damaged  
Replace

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	Fault