



VEHICLE INSPECTION REPORT

LL16YNV

BMW X3 xDrive20d M Sport 5dr Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/04/2016	Body Style	Estate	Last service miles	13,593
Year	2016	Keys	2	MOT Due	08/10/2026
Mileage	98,136 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Electronic & Paper	Gears	8
Colour	GREY	Number of stamps	1		
VIN	WBAWZ520400T54708	Last service date	09/10/2017		

Last service 09/10/2017 at 13,593 miles- 1 service recorded on on-board system EML light is on car has been plugged in and detects
 O2 sensor reference voltage circuit open bank1 sensor 2
 Ho2s heater control circuit bank 1 sensor 2
 Mass or volume air flow a circuit range preference air flow too high

Multiple panels will require machine polish

Tyres

NSF	WESTLAKE	4.0mm
NSR	BUDGET	5.0mm
OSF	WESTLAKE	3.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Dented
With Paint Damage



4: Door osr
Dented
Over 30mm



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



9: Tailgate
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Door nsr
Chipped
1 To 5



14: Door nsf
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
25 to 100mm Thru Paint



17: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK