



**WN12BYK**

## Seat Leon 1.6 TDI CR SE Copa 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	28/03/2012	Body Style	Hatchback	Last service miles	74,650
Year	2012	Keys	2	MOT Due	08/12/2026
Mileage	85,858 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	4	Doors	5
VIN	VSSZZZ1PZCR054113	Last service date	04/01/2022		

Last service 04/01/2022 at 74,650 miles- 4 services Airbag light is on  
 Service due message displayed  
 Some panels require machine polish

### Tyres

NSF	NEXEN	4.0mm
NSR	SAILUN	5.0mm
OSF	NEXEN	4.0mm
OSR	SAILUN	5.0mm

### Spare

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Paint Flake



3: Wing nsf  
Chipped  
Over 5mm



4: Screen Front  
Cracked  
Replace



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
Over 30mm



7: Door nsf  
Chipped  
1 To 5



8: Door nsr  
Dented  
2 Or Less UpTo 10mm



9: Door nsr  
Scratched  
UpTo 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Door osr  
Dented  
Over 30mm



13: Door osf  
Dented  
Between 10mm + 30mm



14: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK