



VEHICLE INSPECTION REPORT

GK60WZD

Volvo XC60 D5 [205] S 5dr AWD Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	30/09/2010	Body Style	Estate	Last service miles	127,773
Year	2010	Keys	2	MOT Due	27/08/2026
Mileage	138,107 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	6		
VIN	YV1DZ7056B2155819	Last service date	28/02/2025		

£90 ADDITIONAL FEE

last service 28/2/25 @ 127,773 miles (6 main dealer) book & print Some panel require machine polish

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Roof
Dented
Over 30mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osr
Dented
Between 10mm + 30mm



13: Door osf
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK