



# VEHICLE INSPECTION REPORT

**GY10CWN**

## Ford Fusion 1.6 Zetec 5dr [Climate]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**5**

### Details

Reg. date	28/05/2010	Body Style	Hatchback	MOT Due	06/10/2026
Year	2010	Keys	1	Gearbox	MANUAL
Mileage	103,915 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	GREY	Number of stamps	2		
VIN	WF0UXXGAJUAT08699	Last service date	11/06/2024		

last service 11/6/24 mileage not recorded (2 services)  
 spark plugs replaced within full service on 11/6/24 Radio faulty

### Tyres

NSF	HABILEAD	5.0mm
NSR	BUDGET	6.0mm
OSF	HABILEAD	5.0mm
OSR	HABILEAD	5.0mm
Spare		

### Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Alloy wheels
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Holed  
Over 3mm



2: Bonnet  
Scratched  
Over 25mm Thru Paint



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Dented  
Over 30mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
Multiple Chips



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Tailgate  
Chipped  
1 To 5



11: Qtr Panel osr  
Dented  
Over 30mm



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Door Moulding osf  
Scratched (Painted)  
Over 25mm Thru Paint



15: Door osr  
Dented  
Between 10mm + 30mm



16: Door osf  
Chipped  
Edge Chip



17: Wing osf  
Scratched  
Over 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm



19: Roof  
Dented  
Over 30mm



20: Seat Back Cover nsf  
Scuffed  
Over 25mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK