



# VEHICLE INSPECTION REPORT

**DU66UKK**

## Vauxhall Mokka 1.4T SE 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	12/09/2016	Body Style	Hatchback	Last service miles	84,107
Year	2016	Keys	2	MOT Due	11/09/2026
Mileage	92,951 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	8	Doors	5
VIN	W0LJD7E85GB743847	Last service date	04/09/2025		

last service 4/9/25 @ 84,107 miles (8 services 7 main dealer)

### Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

## Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- PAS
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm




2: Bonnet  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Over 50mm



4: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



5: Door nsf  
Scratched  
UpTo 25mm Thru Paint



6: Door nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Wheel osr  
Scratched  
Up To 50mm



11: Door osr  
Dented  
Between 10mm + 30mm



12: Door osf  
Dented  
2 Or Less UpTo 10mm



13: Door osf  
Scratched  
UpTo 25mm Thru Paint



14: Wing osf  
Chipped  
1 To 5



15: Wheel of  
Scratched  
Over 50mm



16: Bumper Front  
Chipped  
1 To 5



17: Roof  
Chipped  
Edge Chip

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK