



VEHICLE INSPECTION REPORT

DY66GXA

Vauxhall Astra 1.0T 12V ecoFLEX SRi 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/09/2016	Keys	1	CAP Clean	£2,525.00
Year	2016	Service history	Yes	CAP Average	£2,075.00
Mileage	95,243 Miles Warranted	Service documents	Service Book	CAP Below	£1,625.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	SILVER	Last service date	08/08/2024	Gears	5
VIN	W0LBF6EA2GG158481	Last service miles	89,832	Doors	5
Body Style	Hatchback	MOT Due	30/08/2025		

£100 ADDITIONAL FEE

Last Service - 08.08.2024 at 89832 miles (3 services)

Clutch Replaced 31.10.2023 @ 83175 miles

Eml on

Tyres


NSF	MICHELIN	2.0mm
NSR	KUMHO	OK
OSF	BUDGET	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- Rear parking sensor
- Digital radio
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Not Thru Paint



3: Wheel nsr
Scratched
Over 50mm



4: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



5: Door nsr
Chipped
Multiple Chips



6: Door nsf
Chipped
1 To 5



7: Wing nsf
Poor Previous Repair
Poor Paint



8: Wheel nsf
Scratched
Over 50mm



9: Bonnet
Chipped
Multiple Chips



10: Bumper Front
Cracked
UpTo 25mm



11: Wheel osf
Scratched
Over 50mm



12: Door osf
Chipped
1 To 5



13: Door osr
Poor Previous Repair
Poor Paint



14: Wheel osr
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK