



# VEHICLE INSPECTION REPORT

**MT10FHY**

## Volkswagen Golf 1.4 S 5dr

nama  
GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	13/07/2010	Body Style	Hatchback	MOT Due	27/03/2027
Year	2010	Keys	1	Gearbox	MANUAL
Mileage	132,738 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Petrol	Number of stamps	3	Doors	5
Colour	GREY	Last service date	02/01/2015		
VIN	WVWZZZ1KZAW400774	Last service miles	19,959		

Last service 02/01/2015 at 19,959 miles- 3 main dealer services confirmed by Group One VW, Altrincham Some panels require machine polish

### Tyres

NSF	AUTOGREEN	5.0mm
NSR	BUDGET	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Side airbags
- Steel wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Steering wheel mounted controls
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint




2: Bumper Front  
Poor Previous Repair  
Paint Flake



3: Wing nsf  
Dented  
Over 30mm




4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



5: Screen Front  
Cracked  
Replace



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



9: Other  
N/A  
N/A



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Tailgate  
Poor Previous Repair  
Poor Paint



12: Qtr Panel nsr  
Dented  
With Paint Damage



13: Door osr  
Chipped  
1 To 5



14: Door osf  
Scratched  
Over 25mm Thru Paint



15: Wing of  
Chipped  
1 To 5

16: Bumper Front  
Insecure  
Action Required

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK