



VEHICLE INSPECTION REPORT

VN64XMP

Nissan Pulsar 1.5 dCi N-Tec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2014	Body Style	Hatchback	Last service miles	155,759
Year	2014	Keys	2	MOT Due	11/03/2027
Mileage	160,778 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	13	Doors	5
VIN	VSKDAAC13U0008637	Last service date	19/11/2025		

£100 ADDITIONAL FEE

LAST SERVICE 19/11/2025 @ 155,759 MILES (13 SERVICES, 5 MAIN DEALER - BOOK & PRINT) Engine misfires

Tyres



NSF	SUNNY	5.0mm
NSR	LAUFENN	5.0mm
OSF	SUNNY	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Chipped
1 To 5



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Dented
With Paint Damage



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Dented
With Paint Damage



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Over 30mm



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK