



# VEHICLE INSPECTION REPORT

**MJ12REU**

## Seat Leon 1.6 TDI CR SE Copa 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
4

### Details

Reg. date	12/06/2012	VIN	VSSZZZ1PZCR066390	CAP Average	£1,625.00
Year	2012	Body Style	Hatchback	CAP Below	£1,200.00
Mileage	81,701 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	01/11/2025	Gears	5
Colour	WHITE	CAP Clean	£2,050.00	Doors	5

£100 ADDITIONAL FEE Bulb light on dash

### Tyres

NSF	FALKEN	3.0mm
NSR	GOODYEAR	2.0mm
OSF		3.0mm
OSR	GT RADIAL	3.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Paint Flake



2: Bumper Front  
Poor Previous Repair  
Paint Flake





3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsr  
Chipped  
1 To 5



5: Door nsr  
Chipped  
1 To 5



6: Wheel nsr  
Scratched  
Over 50mm



7: Qtr Panel nsr  
Dented  
Over 30mm



8: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



9: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



10: Wheel osr  
Scratched  
Up To 50mm



11: Door osr  
Chipped  
1 To 5



12: Door osf  
Chipped  
Multiple Chips



13: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



14: Wheel osf  
Scratched  
Up To 50mm





15: Sill ns  
Dented  
With Paint Damage

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK