



VEHICLE INSPECTION REPORT

GF12TYZ

Skoda Octavia 2.0 TDI CR SE Plus 5dr

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	07/06/2012	Body Style	Estate	Last service miles	134,457
Year	2012	Keys	2	MOT Due	12/08/2026
Mileage	139,182 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREY	Number of stamps	6		
VIN	TMBHE21Z6C2085867	Last service date	09/01/2026		

£90 ADDITIONAL FEE

last service 9/1/26 @ 134,457 miles (6 services 1 main dealer) print
 replaced clutch and tensioner on 17/1/25 @ 114,929 miles

Tyres

NSF	BRIDGESTONE	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Heated door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Door Pad osf
Scuffed
Over 25mm




2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Wing nsf
Chipped
Over 5mm




5: Wheel nsf
Scratched
Over 50mm




6: Door nsf
Dented
Over 30mm




7: Door nsr
Dented
Over 30mm




8: Wheel nsr
Scratched
Over 50mm




9: Sill ns
Dented
Over 30mm




10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: Tailgate
Dented
With Paint Damage




13: Screen Rear
Scratched
Over 30mm




14: Roof
Dented
Over 30mm




15: Wheel osr
Scratched
Over 50mm




16: Qtr Panel osr
Rusted
Over 5mm




17: Door osr
Dented
With Paint Damage




18: Door osf
Chipped
Edge Chip




19: Door Mirror Glass os
Broken
Replace




20: Flasher Side Repeater os
Broken
Replace




21: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint




22: Wheel osf
Scratched
Over 50mm




23: Wing osf
Chipped
1 To 5



24: Screen Front
Chipped
Over 10mm



25: Tyre nsf
Damaged
Replace



26: Fascia Trim
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK