



VEHICLE INSPECTION REPORT

GP16PVJ

Skoda Fabia 1.2 TSI SE L 5dr

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	09/04/2016	Body Style	Estate	Last service miles	137,236
Year	2016	Keys	2	MOT Due	15/10/2026
Mileage	146,733 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	12		
VIN	TMBKN6NJ5GZ163862	Last service date	30/04/2025		

Last Service - 30.04.2025 at 137236 miles (12 services)
 Cambelt replaced 15.05.2024 @ 121783 Miles One key broken

Tyres


NSF	CONTINENTAL	3.0mm
NSR	FALKEN	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Full size spare wheel
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Dented
With Paint Damage



3: Other
N/A
N/A



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
Edge Chip



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
Rusted



12: C Post os
Dented
Between 10mm + 30mm



13: Wheel osr
Scratched
Up To 50mm



14: Door osr
Scratched
Up To 25mm Thru Paint



15: Door osr
Dented
Between 10mm + 30mm



16: Door osf
Dented
With Paint Damage



17: A Post os
Chipped
1 To 5




18: Wing nsf
Dented
Over 30mm



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm



21: Roof
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK