



VEHICLE INSPECTION REPORT

HG14WYB

Kia Carens 1.7 CRDi 3 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	14/08/2014	Body Style	MPV	Last service miles	143,197
Year	2014	Keys	1	MOT Due	15/12/2026
Mileage	165,516 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	5		
VIN	KNAHU815LF7086405	Last service date	17/08/2022		

Last Service -17.08.2022 at 143197 miles (5services) Roof will not open
 Boot will not open

Tyres

NSF	SUNNY	Damaged
NSR	BRIDGESTONE	Damaged
OSF	BUDGET	5.0mm
OSR	FARROAD	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Radio/CD
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Seat Back Cover osf
Torn
Over 3mm



3: Seat Back Cover nsf
Torn
Over 3mm



4: Door Pad nsf
Broken
Replace



5: Bonnet
Chipped
Multiple Chips



6: Bumper Front Grill
Broken
Replace



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Wheel nsf
Scratched
Over 50mm



9: Wing nsf
Chipped
Over 5mm



10: Door nsf
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Other
N/A
N/A



16: B Post os
Dented
Over 30mm



17: Qtr Panel osr
Rusted
Over 5mm



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Poor Previous Repair
Rippled UpTo 30%



20: Door osf
Chipped
Edge Chip



21: Door osf
Dented
Between 10mm + 30mm



22: Wheel osf
Scratched
Over 50mm



23: Tyre nsf
Damaged
Replace



24: Tyre nsr
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK