



VEHICLE INSPECTION REPORT

FM14EJE

Skoda Yeti Outdoor 2.0 TDI CR [140] Laurin + Klement 4x4 5dr DSG

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	15/07/2014	Body Style	Hatchback	Last service miles	133,789
Year	2014	Keys	2	MOT Due	14/07/2026
Mileage	136,212 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREEN	Number of stamps	13	Doors	5
VIN	TMBMD75L7F6010323	Last service date	22/01/2026		

£90 ADDITIONAL FEE.

Last service 22/01/2026 at 133,789 miles- 13 services (3 main dealer) Power steering light on
 Abs light on
 Traction light on

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wheel osr
Corroded
Light



3: Qtr Panel osr
Chipped
1 To 5



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear Moulding
Broken
Replace



6: Wheel nsr
Corroded
Light



7: Door nsf
Dented
Over 2 UpTo 10mm



8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Door nsf
Scratched
UpTo 25mm Thru Paint



10: Wheel nsf
Corroded
Light



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bonnet
Chipped
1 To 5



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK