



VEHICLE INSPECTION REPORT

BT16GJX

Kia Sportage 1.7 CRDi ISG 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	24/05/2016	Body Style	Estate	Last service miles	48,204
Year	2016	Keys	2	MOT Due	11/05/2026
Mileage	69,065 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	5		
VIN	U5YPH815LGL087939	Last service date	12/05/2023		

£100 ADDITIONAL FEE

LAST SERVICE 12/05/2023 @ 48,204 MILES (5 SERVICES, ALL MAIN DEALER) Noisy engine
 Service light on
 Car smoking

Tyres

NSF	PACE	5.0mm
NSR	HANKOOK	5.0mm
OSF	PACE	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel Arch Extension ns
Missing
Replace



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Door osr
Chipped
Edge Chip



10: Wheel osr
Scratched
Up To 50mm



11: Door osf
Chipped
Edge Chip



12: Door osf
Dented
2 Or Less UpTo 10mm



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK