

VEHICLE INSPECTION REPORT

GU62ZVA

Hyundai I10 1.2 Active 5dr

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	06/11/2012	Body Style	Hatchback	Last service miles	51,502
Year	2012	Keys	2	MOT Due	01/12/2026
Mileage	73,319 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	10	Doors	5
VIN	MALAN51CLDM256072	Last service date	17/10/2023		

Last service 17/10/2023 at 51502 miles (10 services (5 main dealer). Central locking faulty


Tyres


NSF	FULDA	5.0mm
NSR	FALKEN	5.0mm
OSF	FULDA	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front electric windows
- Rear electric windows
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Folding rear seats
- Rear armrest
- Solid Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Paint Flake



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door osr
Chipped
1 To 5



14: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK