



VEHICLE INSPECTION REPORT

GL12DYV

Skoda Octavia 1.4 TSI Elegance 5dr DSG

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	11/06/2012	Body Style	Hatchback	Last service miles	66,290
Year	2012	Keys	2	MOT Due	02/04/2027
Mileage	95,795 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	9	Doors	5
VIN	TMBBJ21Z5C2197545	Last service date	11/04/2022		

£90 ADDITIONAL FEE.

LAST SERVICE 11/04/2022 @ 66,290 MILES (9 SERVICES, ALL MAIN DEALER)

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	5.0mm
OSF	HABILEAD	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Screen Front
Scratched
Over 30mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Scratched
Up To 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Over 30mm



9: Sill ns
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
Over 5mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Chipped
Edge Chip



17: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



18: Sill ns
Dented
With Paint Damage



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK