



# VEHICLE INSPECTION REPORT

**GK14AEW**

## Kia Ceed 1.6 CRDi 3 EcoDynamics 5dr



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	30/04/2014	Body Style	Hatchback	Last service miles	129,412
Year	2014	Keys	2	MOT Due	30/06/2026
Mileage	164,898 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	11	Doors	5
VIN	U5YHN516LEL119853	Last service date	24/10/2023		

£90 ADDITIONAL FEE.

NEW CLUTCH PUT IN @ 115,103 MILES ON 14/02/2025.

LAST SERVICE 24/10/2023 @ 129,412 MILES (11 SERVICES, 9 MAIN DEALER)

### Tyres


NSF
NSR
OSF
OSR
Spare

## Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Between 10mm + 30mm



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Dented  
Over 30mm



7: Door nsr  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Dented  
Between 10mm + 30mm



11: Qtr Panel osr  
Poor Previous Repair  
Poor Paint




12: Door osr  
Scratched  
Over 25mm Thru Paint



13: Sill os  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Dented  
Over 30mm



15: Wing osf  
Chipped  
Multiple Chips



16: Wheel osf  
Scratched  
Over 50mm



17: A Post os  
Scratched  
Over 25mm Thru Paint



18: Screen Front  
Chipped  
Over 10mm



19: Roof  
Scratched  
Over 25mm Thru Paint



20: Carpets Front  
Holed  
Over 3mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK