



VEHICLE INSPECTION REPORT

BV64FCD

Vauxhall Meriva 1.4i 16V Exclusiv 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	22/09/2014	Body Style	MPV	Last service miles	64,473
Year	2014	Keys	2	MOT Due	22/11/2026
Mileage	65,366 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	11		
VIN	W0LSD9EC5F4013735	Last service date	13/11/2025		

last service 13/11/25 @ 64,473 miles (11 services 1 main dealer)

Tyres

NSF	TRIANGLE	5.0mm
NSR	TRIANGLE	5.0mm
OSF	TRIANGLE	5.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Chipped
1 To 5



4: Screen Front
Chipped
UpTo 10mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm




11: Bumper Rear
Scratched
25 to 100mm Thru Paint




12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
With Paint Damage



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK