



VEHICLE INSPECTION REPORT

GD08FBZ

Citroen C4 Grand Picasso 1.6HDi 16V SX 5dr EGS

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	27/06/2008	Body Style	MPV	Last service miles	81,100
Year	2008	Keys	2	MOT Due	21/06/2026
Mileage	83,393 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8		
VIN	VF7UA9HZH45252642	Last service date	29/05/2025		

£65 ADDITIONAL FEE

MILEAGE INPUT ERROR ON MOT 22/06/2020 @ 41,284 MILES

LAST SERVICE 29/05/2025 @ 81,100 MILES (8 SERVICES, 5 MAIN DEALER) Starter motor whinny

Service spanner displayed

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	6.0mm

Spare

Features


- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Steel wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Other
N/A
N/A



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: A Post ns
Rusted
Over 5mm



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Wing osf
Chipped
1 To 5



15: A Post os
Rusted
Over 5mm



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Roof
Chipped
Edge Chip



18: Tailgate
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK