



# VEHICLE INSPECTION REPORT

**WF56CDE**

## Vauxhall Astra 1.4i 16V SXi 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE 5

### Details

Reg. date	26/09/2006	Body Style	Hatchback	Last service miles	125,201
Year	2006	Keys	1	MOT Due	18/11/2026
Mileage	128,406 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	SILVER	Number of stamps	3	Doors	3
VIN	W0LOAHL0875006094	Last service date	19/09/2024		

last service 19/9/24 @ 125,201 miles (3 services)

### Tyres

NSF	SAILUN	5.0mm
NSR	BUDGET	5.0mm
OSF	DUNLOP	5.0mm
OSR	BUDGET	5.0mm
Spare		

### Features


- PAS
- Electric door mirrors
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking
- Rear wiper
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Radio/CD
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



4: A Post os  
Chipped  
1 To 5



5: Sill os  
Dented  
With Paint Damage



6: Door osf  
Scratched  
UpTo 25mm Thru Paint



7: Qtr Panel osr  
Chipped  
1 To 5



8: Wheel osr  
Scratched  
Over 50mm



9: Bumper Rear  
Poor Previous Repair  
Poor Paint



10: Tailgate  
Dented  
Between 10mm + 30mm



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Chipped  
1 To 5



13: Wing nsf  
Dented  
With Paint Damage



14: Wheel nsf  
Scratched  
Over 50mm



15: Bumper Front  
Cracked  
Over 25mm



16: Bonnet  
Chipped  
Multiple Chips



17: Roof  
Dented  
With Paint Damage

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK