

VEHICLE INSPECTION REPORT

LY16BVA

Nissan Qashqai 1.2 DiG-T Tekna [Non-Panoramic] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	11/06/2016	Body Style	Hatchback	Last service miles	48,821
Year	2016	Keys	2	MOT Due	31/05/2026
Mileage	54,184 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BRONZE	Number of stamps	7	Doors	5
VIN	SJNFEAJ11U1718364	Last service date	16/05/2025		

£90 ADDITIONAL FEE.

Last service 16/05/2025 at 48,821 miles- 7 services (4 main dealer) Engine tapping
Reverse camera faulty

Tyres

NSF	ACCELERA	6.0mm
NSR	ACCELERA	6.0mm
OSF	GT RADIAL	4.0mm
OSR	ACCELERA	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Insecure
Action Required



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Lamp osr
Broken
Replace



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
Multiple Chips



14: Door osf
Dented
Between 10mm + 30mm



15: Door osf
 Scratched
 UpTo 25mm Thru Paint



16: Wing osf
 Scratched
 UpTo 25mm Thru Paint



17: Door Mirror Assy osf
 Scratched (Painted)
 UpTo 25mm Thru Paint



18: Wheel osf
 Scratched
 Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		