



VEHICLE INSPECTION REPORT

GX15RRU

Ford B-Max 1.6 Zetec 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2015	Keys	2	CAP Clean	£4,075.00
Year	2015	Service history	Yes	CAP Average	£3,550.00
Mileage	46,971 Miles Warranted	Service documents	Service Book	CAP Below	£3,025.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	07/10/2021	Gears	5
VIN	WF0KXXERJKFK70427	Last service miles	26,935		
Body Style	MPV	MOT Due	12/10/2025		

£100 ADDITIONAL FEE. Last Service: 07/10/2021 at 26935 miles. (5 services (3 main dealer)). Book & print.
Rear bumper misaligned vibration at idle

Tyres

NSF	RAPID	2.0mm
NSR	FIRESTONE	Illegal
OSF	BUDGET	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Trip computer
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Boot Lid
Chipped
1 To 5



2: Bumper Rear
Cracked
Over 25mm




3: Bumper Reflector osr
Broken
Replace



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




5: Wheel nsr
Scratched
Up To 50mm



6: Door nsr
Chipped
1 To 5




7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Chipped
1 To 5

No Image

9: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Wing nsf
Chipped
1 To 5



13: Bonnet
Dented
With Paint Damage

No Image

10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



12: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



15: Bumper Front
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Chipped
1 To 5

No Image

18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Not Thru Paint



19: Door osf
Dented
Over 2 UpTo 10mm

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



21: Door osr
Scratched
Over 25mm Not Thru Paint

22: Wheel osr
Scratched
Up To 50mm

No Image

23: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK