



# VEHICLE INSPECTION REPORT

**AO16NKT**

## Ford Fiesta 1.0 EcoBoost Zetec Black 5dr

nama  
GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	31/03/2016	Body Style	Hatchback	Last service miles	61,587
Year	2016	Keys	2	MOT Due	19/04/2027
Mileage	92,949 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	1	Doors	5
VIN	WF0DXXGAKDGB18850	Last service date	18/04/2024		

£100 ADDITIONAL FEE.  
 LAST SERVICE 18/04/2024 @ 61,587 MILES (1 SERVICE)

### Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint




3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Dented  
With Paint Damage



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage




8: Wheel nsr  
Scratched  
Up To 50mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Qtr Panel osr  
Dented  
With Paint Damage



11: Door osr  
Scratched  
Over 25mm Thru Paint



12: Door osf  
Scratched  
Over 25mm Thru Paint



13: Wing nsf  
Scratched  
Over 25mm Thru Paint



14: Wheel osf  
Scratched  
Over 50mm



15: Screen Front  
Cracked  
Replace

16: Roof  
Chipped  
1 To 5

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK