



VEHICLE INSPECTION REPORT

BU65BVK

Nissan X-Trail 1.6 dCi N-Tec 5dr Xtronic [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	12/10/2015	Body Style	Estate	Last service miles	36,672
Year	2015	Keys	2	MOT Due	24/06/2026
Mileage	64,498 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	ORANGE	Number of stamps	1		
VIN	JN1JCAT32U0013199	Last service date	06/06/2023		

£90 ADDITIONAL FEE.

Last service 06/06/2023 at 36672 miles (1 service) Waning oil sensor faulty message displayed


Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check




Damage Photos




1: Wheel of
Corroded
Light




2: Wing of
Scratched
Over 25mm Thru Paint




3: Door osf
Chipped
1 To 5




4: Door osf
Chipped
Edge Chip




5: Door osr
Chipped
1 To 5




6: Wheel osr
Corroded
Light




7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




8: Bumper Rear
Scratched
Over 100mm Thru Paint




9: Tailgate
Chipped
Multiple Chips




10: Lamp nsr
Broken
Replace




11: Qtr Panel nsr
Dented
Over 30mm




12: Wheel nsr
Corroded
Light




13: Door nsr
Chipped
Edge Chip




14: Door nsr
Chipped
1 To 5




15: Door nsr
Scratched
Over 25mm Not Thru Paint




16: Door nsf
Chipped
Edge Chip




17: Door nsf
Scratched
Over 25mm Not Thru Paint




18: Wing nsf
Chipped
1 To 5




19: Wing nsf
Scratched
Over 25mm Not Thru Paint




20: Wheel nsf
Corroded
Light




21: Bumper Front
Scratched
25 to 100mm Thru Paint



22: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



23: Bonnet
Chipped
1 To 5



24: Switches And Controls
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		