



VEHICLE INSPECTION REPORT

GY71PXS

Seat Ibiza 1.0 TSI 95 Xcellence 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/02/2022	Body Style	Hatchback	Last service miles	17,872
Year	2022	Keys	2	MOT Due	01/04/2027
Mileage	37,924 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	1	Doors	5
VIN	VSSZZKJZNR019972	Last service date	03/06/2024		

£90 ADDITIONAL FEE.

Last service 03/06/2024 at 17,872 miles- 1 main dealer service. Print Service due message displayed

Tyres

NSF	NEXEN	1.8mm
NSR	NEXEN	3.0mm
OSF	NEXEN	1.8mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Wheel of
Scratched
Over 50mm




2: Wing of
Chipped
1 To 5




3: Door osf
Scratched
Over 25mm Thru Paint




4: Door osr
Dented
With Paint Damage




5: Wheel osr
Scratched
Over 50mm




6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




7: Bumper Rear
Scratched
Over 100mm Thru Paint




8: Tailgate
Dented
Over 30mm




9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm




10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




11: Wheel nsr
Scratched
Over 50mm




12: Door nsr
Dented
2 Or Less UpTo 10mm




13: Door nsr
Chipped
1 To 5




14: Door nsr
Scratched
Over 25mm Not Thru Paint




15: Door nsf
Dented
With Paint Damage




16: Wing nsf
Dented
2 Or Less UpTo 10mm




17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Bonnet
Dented
With Paint Damage



20: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK