



# VEHICLE INSPECTION REPORT

**KE17GYA**

## Seat Leon 1.4 EcoTSI 150 FR Technology 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	14/07/2017	Body Style	Hatchback	Last service miles	79,430
Year	2017	Keys	2	MOT Due	04/07/2026
Mileage	83,941 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	MAUVE/PURPLE	Number of stamps	6	Doors	5
VIN	VSSZZZ5FZJR010469	Last service date	10/07/2025		

£90 ADDITIONAL FEE.

Last service 10/07/2025 at 79430 miles (6 services (3 main dealer). Some panels require machine polish

### Tyres

NSF	BRIDGESTONE	4.0mm
NSR	MICHELIN	5.0mm
OSF	BRIDGESTONE	4.0mm
OSR	MICHELIN	5.0mm
Spare		

### Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

### Photos






## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Chipped  
Multiple Chips




3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Chipped  
1 To 5



5: A Post ns  
Chipped  
1 To 5



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Over 50mm



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



11: Tailgate  
Scratched  
UpTo 25mm Thru Paint



12: Qtr Panel osr  
Dented  
Between 10mm + 30mm



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Wheel osr  
Scratched  
Over 50mm



15: Door osf  
Chipped  
1 To 5



16: Wing osf  
Scratched  
UpTo 25mm Thru Paint



17: Wheel osf  
Scratched  
Up To 50mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK