



VEHICLE INSPECTION REPORT

RO13VNS

Volkswagen Golf 1.6 TDI 105 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/05/2013	Body Style	Hatchback	Last service miles	113,226
Year	2013	Keys	2	MOT Due	03/10/2026
Mileage	119,722 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	9	Doors	5
VIN	WVVZZZAUZDW080391	Last service date	04/10/2025		

Last service 04/10/2025 at 113,226 miles- 9 services (3 main dealer)
 Cambelt and water pump replaced 09/11/2023 at 93,556 miles Abs and traction control light is on
 Parking sensors faulty

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Blind spot information
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Multiple Chips



6: Door nsr
Chipped
Multiple Chips



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
1 To 5



13: Door osf
Chipped
Edge Chip




14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm



16: Roof
Scratched
Over 25mm Thru Paint



17: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK