



VEHICLE INSPECTION REPORT

GF10FYH

Volvo XC90 2.4 D5 R DESIGN SE Premium 5dr Geartronic

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Buyer To Apply

Details

Reg. date	29/06/2010	Body Style	Estate	Last service miles	116,473
Year	2010	Keys	2	MOT Due	28/10/2026
Mileage	171,096 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	6
Colour	SILVER	Number of stamps	1		
VIN	YV1CT7146A1564893	Last service date	03/08/2022		

V5 INVALID

last service 3/8/22 @ 116,473 miles (1 service) confirmed by Testsandtyres Some panels required machine polish

Engine misfires

Engine system service urgent message displayed

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Chipped
Multiple Chips



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Dented
With Paint Damage




10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osf
Chipped
Edge Chip



13: Screen Front
Chipped
Up To 10mm



14: Bumper Rear Moulding
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK