



# VEHICLE INSPECTION REPORT

**BF17HCV**

## Vauxhall Adam 1.2i Jam 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/03/2017	Body Style	Hatchback	Last service miles	75,649
Year	2017	Keys	1	MOT Due	16/02/2027
Mileage	82,404 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLUE	Number of stamps	4	Doors	3
VIN	W0L0MAP08H6055282	Last service date	13/08/2025		

### £90 ADDITIONAL FEE

Last service 13/08/2025 at 75,649 miles- 4 services Some panel require machine polish  
 Service due message displayed

### Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	4.0mm

Spare

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bumper Front  
Poor Previous Repair  
Paint Flake



2: Bonnet  
Scratched  
Over 25mm Thru Paint



3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: A Post ns  
Chipped  
1 To 5



6: Screen Front  
Chipped  
UpTo 10mm



7: Door nsf  
Dented  
Between 10mm + 30mm



8: Door nsf  
Chipped  
1 To 5



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Wheel nsr  
Scratched  
Over 50mm




11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



12: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osf  
Dented  
Over 30mm



15: Roof  
Chipped  
1 To 5



16: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



17: Wheel osf  
Scratched  
Over 50mm



18: A Post os  
Chipped  
1 To 5

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK