

VEHICLE INSPECTION REPORT

VN71AJO

Toyota Yaris 1.5 Hybrid Design 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present

nama
GRADE
4

Details

Reg. date	12/01/2022	Body Style	Hatchback	Last service miles	75,072
Year	2022	Keys	2	MOT Due	11/01/2027
Mileage	79,031 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	WHITE	Number of stamps	6	Doors	5
VIN	VNKKBAC330A203254	Last service date	28/07/2025		

Last service 28/07/2025 at 75,072 miles- 6 main dealer services

Tyres


NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Dented
UpTo 30mm (Alloy)



4: Door nsf
Dented
Between 10mm + 30mm



5: Wheel nsr
Scratched
Over 50mm



6: Qtr Panel nsr
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osr
 Scratched
 Over 25mm Thru Paint



10: Door osf
 Dented
 Between 10mm + 30mm



11: Wheel osf
 Scratched
 Over 50mm



12: Door osr
 Hole
 Over 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK