



VEHICLE INSPECTION REPORT

GV19PVJ

Mercedes-Benz A Class A180d AMG Line Premium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	29/04/2019	Body Style	Hatchback	Last service miles	32,298
Year	2019	Keys	2	MOT Due	18/06/2026
Mileage	39,428 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WDD1770032V028874	Last service date	24/03/2025		

£90 ADDITIONAL FEE

Last service at 24/03/2025 at 32,298 miles- 6 main dealer services. Print Service due message displayed
Driveshaft noisy on full lock

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking

Photos





Condition Check




Damage Photos




1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Door nsf
Scratched
Over 25mm Thru Paint




6: Door nsr
Dented
Between 10mm + 30mm




7: Door nsr
Scratched
UpTo 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Chipped
1 To 5




10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Qtr Panel osr
Scratched
Over 25mm Thru Paint




12: Wheel osr
Scratched
Over 50mm




13: Door osr
Dented
With Paint Damage




14: Wheel osf
Scratched
Over 50mm



15: Wing of
Scratched
Up To 25mm Thru Paint



16: Door of
Chipped
Edge Chip



17: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK