



# VEHICLE INSPECTION REPORT

**KS63GVU**

## Seat Leon 2.0 TDI 184 FR 5dr [Technology Pack]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	20/01/2014	Keys	1	CAP Clean	£2,850.00
Year	2014	Service history	Yes	CAP Average	£2,400.00
Mileage	136,156 Miles Warranted	Service documents	Service Book	CAP Below	£1,925.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	WHITE	Last service date	09/03/2024	Gears	6
VIN	VSSZZZ5FZER017444	Last service miles	118,919	Doors	5
Body Style	Hatchback	MOT Due	22/09/2025		

CAMBELT REPLACED 15/06/2022 @ 106343 MILES Last service 09/03/2024 @ 118919 miles (10 SERVICES 8 MAIN DEALER) book + print Both front windows don't work

### Tyres


NSF	FIRESTONE	5.0mm
NSR	NEXEN	3.0mm
OSF	FIRESTONE	4.0mm
OSR	CONTINENTAL	3.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
Edge Chip





3: Door osr  
Scratched  
Over 25mm Not Thru Paint



4: Qtr Panel osr  
Dented  
With Paint Damage



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Door nsr  
Chipped  
Edge Chip



7: Door nsr  
Dented  
Between 10mm + 30mm



8: Door nsf  
Chipped  
Edge Chip




9: Wing nsf  
Chipped  
1 To 5



10: Bumper Front  
Scratched  
Over 100mm Thru Paint



11: Bonnet  
Poor Previous Repair  
Poor Paint



12: Screen Front  
Chipped  
UpTo 10mm



13: Roof  
Chipped  
1 To 5



14: Sill os  
Scratched  
Over 25mm Not Thru Paint



15: Seat Base Cover osf  
Torn  
UpTo 3mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK