



# VEHICLE INSPECTION REPORT

**SM63UVR**

## Mitsubishi Outlander 2.2 DI-D GX4 5dr

nama  
GRADE  
**5**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	21/02/2014	Body Style	Estate	Last service miles	120,451
Year	2014	Keys	2	MOT Due	25/01/2027
Mileage	124,707 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	8		
VIN	JMAXJGF6WDZ401677	Last service date	24/06/2025		

£100 ADDITIONAL FEE

LAST SERVICE 24/06/2025 @ 120,451 MILES (8 SERVICES, 3 MAIN DEALER) Engine noisy

### Tyres

NSF	ROYALBLACK	5.0mm
NSR	BUDGET	Damaged
OSF	ROYALBLACK	5.0mm
OSR	ROTALLA	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Dented  
With Paint Damage



2: Door osf  
Chipped  
Edge Chip



3: Door osf  
Scratched  
Up To 25mm Thru Paint



4: Door osf  
Chipped  
1 To 5



5: Door osr  
Dented  
With Paint Damage



6: Qtr Panel osr  
Dented  
Over 30mm



7: Wheel osr  
Scratched  
Up To 50mm



8: Other  
N/A  
N/A



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Tailgate  
Chipped  
1 To 5



11: Qtr Panel nsr  
Dented  
With Paint Damage



12: Wheel nsr  
Scratched  
Over 50mm



13: Door nsr  
Dented  
With Paint Damage



14: Door nsf  
Scratched  
Up To 25mm Thru Paint



15: Door nsf  
Chipped  
Edge Chip



16: Door nsf  
Chipped  
1 To 5



17: Wing nsf  
Chipped  
1 To 5



18: Wheel nsf  
Scratched  
Over 50mm




19: Bumper Front  
Hole  
UpTo 25mm



20: Other  
N/A  
N/A



21: Bonnet  
Chipped  
Multiple Chips



22: Roof  
Rusted  
Over 5mm



23: Wheel ofsf  
Scratched  
Over 50mm



24: Carpets Front  
Soiled  
Light



25: Seat Back Cover ofsf  
Scuffed  
Over 25mm



26: Carpets Rear  
Soiled  
Heavy



27: Tyre nsr  
 Damaged  
 Replace

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
 Average

**Upholstery Condition**  
**Odour**

Average  
 No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		