



# VEHICLE INSPECTION REPORT

LL66PDK

## Renault Captur 0.9 TCE 90 Dynamique S Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
3

### Details

Reg. date	30/11/2016	Keys	2	CAP Average	£3,200.00
Year	2016	Service history	Yes	CAP Below	£2,650.00
Mileage	72,589 Miles Warranted	Service documents	Service Book	Gearbox	MANUAL
Fuel Type	Petrol	Number of stamps	7	Gears	5
Colour	BLUE/BLACK	Last service date	14/04/2025	Doors	5
VIN	VF12RD11A56719401	MOT Due	29/11/2025		
Body Style	Hatchback	CAP Clean	£3,725.00		

Last Service - 14.04.2025 at unknown miles (7 services) Exhaust leak and noisy engine

### Tyres

NSF	LAUFENN	2.0mm
NSR	AVON	4.0mm
OSF	LAUFENN	2.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Boot Lid  
Dented  
Over 2 UpTo 10mm




2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint





3: Wheel osr  
Corroded  
Light



4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



5: Door osr  
Dented  
Over 2 UpTo 10mm



6: Door osr  
Dented  
Over 2 UpTo 10mm



7: Wheel osf  
Corroded  
Light



8: Bumper Front  
Chipped  
Multiple Chips



9: Bonnet  
Chipped  
1 To 5



10: Wheel nsf  
Corroded  
Light



11: Bonnet  
Chipped  
1 To 5

No Image

12: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

No Image

13: Wheel nsf  
Corroded  
Light

No Image

14: Door nsf  
Dented  
Over 2 UpTo 10mm





15: Door nsr  
Scratched  
Over 25mm Thru Paint



16: Wheel nsr  
Scratched  
Over 50mm



17: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK