



VEHICLE INSPECTION REPORT

LG20SVV

Land Rover Range Rover Evoque 2.0 P250 SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/03/2020	Body Style	Estate	Last service miles	81,172
Year	2020	Keys	2	MOT Due	28/02/2027
Mileage	89,143 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Printout	Gears	9
Colour	GREY	Number of stamps	3		
VIN	SALZA2AX3LH085667	Last service date	24/11/2025		

£90 ADDITIONAL FEE

Last service 24/11/2025 at 81,172 miles- 3 services

Tyres


NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wing nsf
Dented
Between 10mm + 30mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint




5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Dented
Between 10mm + 30mm



10: Door osr
Chipped
1 To 5



11: Door osf
Scratched
UpTo 25mm Thru Paint



12: Wing osf
Scratched
UpTo 25mm Thru Paint



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK