



# VEHICLE INSPECTION REPORT

**YH67XOV**

## Suzuki Sx4 S-Cross 1.0 Boosterjet SZ4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	20/10/2017	Keys	2	CAP Clean	£4,625.00
Year	2017	Service history	Yes	CAP Average	£4,000.00
Mileage	94,661 Miles Warranted	Service documents	Service Book	CAP Below	£3,375.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLACK	Last service date	25/10/2024	Gears	5
VIN	TSMJYA02S00514483	Last service miles	87,181	Doors	5
Body Style	Hatchback	MOT Due	30/10/2025		

£65 ADDITIONAL FEE

Last Service - 25.10.2024 at 87181 miles (10 services) Vibration at idle

### Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint




No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Chipped  
1 To 5

No Image

6: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image



7: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Dented  
2 Or Less UpTo 10mm



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Qtr Panel osr  
Poor Previous Repair  
Poor Paint






15: Door osr  
Poor Previous Repair  
Poor Paint



16: Door osf  
Chipped  
1 To 5



17: Wheel osf  
Scratched  
Over 50mm



18: Wing osf  
Scratched  
Over 25mm Not Thru Paint

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK