



VEHICLE INSPECTION REPORT

GX13NLC

Honda CR-V 2.0 i-VTEC SE-T 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	01/03/2013	Body Style	Estate	Last service miles	70,496
Year	2013	Keys	2	MOT Due	Expired
Mileage	76,057 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	12		
VIN	SHSRE5750DU005489	Last service date	29/04/2025		

LAST SERVICE 29/04/2025 @ 70,496 MILES (12 SERVICES, ALL MAIN DEALER)

MOT EXPIRED Stop start warning light display

Tyres

NSF	NEXEN	6.0mm
NSR	NEXEN	6.0mm
OSF	NEXEN	6.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



10: Qtr Panel osf
Scratched
UpTo 25mm Thru Paint



11: Door osf
Scratched
Over 25mm Thru Paint



12: Door osf
Chipped
Multiple Chips



13: Wing osf
Scratched
UpTo 25mm Thru Paint



14: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK