



VEHICLE INSPECTION REPORT

YB61WCZ

Ford S-Max 1.6 EcoBoost Zetec 5dr [Start Stop]

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|------------------------|--------------------|------------|-------------|-----------|
| Reg. date | 15/02/2012 | Keys | 2 | CAP Clean | £2,375.00 |
| Year | 2012 | Service history | Yes | CAP Average | £1,950.00 |
| Mileage | 81,610 Miles Warranted | Service documents | Printout | CAP Below | £1,500.00 |
| Fuel Type | Petrol | Number of stamps | 2 | Gearbox | MANUAL |
| Colour | SILVER | Last service date | 24/07/2024 | Gears | 6 |
| VIN | WF0SXXGBWSCB45430 | Last service miles | 76,627 | | |
| Body Style | MPV | MOT Due | 22/08/2025 | | |

£100 ADDITIONAL FEE. Last Service: 24/07/2024 at 76627 miles. (2 services) Slight noise at idle

Tyres

| | | |
|-------|--------|-------|
| NSF | BUDGET | 4.0mm |
| NSR | BUDGET | Worn |
| OSF | BUDGET | 4.0mm |
| OSR | BUDGET | 4.0mm |
| Spare | | |

Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Handle Inner osf
Damaged
Replace



2: Tyre nsr
Worn
Replace



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Poor Previous Repair
Paint Flake



8: Door nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Chipped
1 To 5



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
UpTo 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Tyre nsr
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |