



VEHICLE INSPECTION REPORT

KF15BYV

Volvo V40 D2 [120] R DESIGN Lux Nav 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/07/2015	Body Style	Hatchback	Last service miles	54,384
Year	2015	Keys	2	MOT Due	07/07/2026
Mileage	58,000 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	9	Doors	5
VIN	YV1MV74L0G2282309	Last service date	17/06/2025		

£90 ADDITIONAL FEE

Last service 17/06/2025 at 54,384 miles- 9 services (4 main dealer) Book and print Eml light on car has been plugged in and detects EGR control at limit

Tyres

NSF	PIRELLI	4.0mm
NSR	AVON	5.0mm
OSF	GREENLAND	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Wing of
Scratched
Up To 25mm Thru Paint



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Wheel osr
Corroded
Light



8: Bumper Rear
Dented
With Paint Damage



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30mm



11: Wheel nsr
Corroded
Light



12: Door nsr
Chipped
1 To 5



13: Door Mirror Assy nsf
Scratched (Painted)
Up To 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Wing nsf
 Scratched
 Over 25mm Thru Paint



16: Door nsf
 Dented
 With Paint Damage



17: Bumper Front
 Scratched
 Over 100mm Thru Paint



18: Bonnet
 Chipped
 1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK