



VEHICLE INSPECTION REPORT

AK13JFY

Volvo XC60 T6 [304] R DESIGN Nav 5dr AWD Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/04/2013	Body Style	Estate	Last service miles	68,458
Year	2013	Keys	2	MOT Due	10/08/2026
Mileage	114,298 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	2		
VIN	YV1DZ90H6D2461469	Last service date	15/09/2021		

£90 ADDITIONAL FEE.

Last Service - 15.09.2021 at 68458 miles (2 services)

Intermittent issues with door handles
 Front suspension knocking

Tyres

NSF	NANKANG	5.0mm
NSR	NANKANG	6.0mm
OSF	NANKANG	6.0mm
OSR	NANKANG	6.0mm

Spare

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos





Condition Check




Damage Photos




1: Bonnet
Chipped
Multiple Chips




2: Number Plate Front
Broken
Replace




3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5




6: Door nsf
Scratched
Over 25mm Thru Paint




7: Door nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




10: Bumper Rear
Scratched
25 to 100mm Thru Paint




11: Tailgate
Scratched
Over 25mm Thru Paint




12: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%




13: Door osr
Poor Previous Repair
Poor Paint




14: Door osf
Chipped
1 To 5




15: Door osf
Dented
2 Or Less UpTo 10mm




16: Roof
Scratched
Over 25mm Thru Paint



17: Screen Front
Chipped
UpTo 10mm



18: Wheel osf
Scratched
Over 50mm



19: Wing of
Scratched
Up To 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK