



VEHICLE INSPECTION REPORT

GJ13VBC

Kia Carens 1.7 CRDi 3 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	16/05/2013	Body Style	MPV	Last service miles	103,216
Year	2013	Keys	2	MOT Due	Expired
Mileage	112,979 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	2		
VIN	KNAHU815LE7010592	Last service date	08/05/2025		

£90 ADDITIONAL FEE

LAST SERVICE 08/05/2025 @ 103,216 MILES (2 SERVICES, BOTH MAIN DEALER)
 MOT EXPIRED

Tyres

NSF	PIRELLI	6.0mm
NSR	GOODYEAR	6.0mm
OSF	PIRELLI	6.0mm
OSR	BARUM	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Front fog lights
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Space saver spare wheel
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Other
N/A
N/A



11: Qtr Panel osr
Chipped
1 To 5



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Scratched
Up To 25mm Thru Paint



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK